S

Micropol

LUBRICANTS

Π

0 R

E

S

®

MISCELLANEOUS APPLICATIONS FILLED BEARINGS

C

A

S

П

| CASE 1: | Pump impeller - sewage treatment |
|--|---|
| BEARING TYPE | Roller bearing, #23052 |
| CONDITIONS: | Sewage in oil bath. |
| Results: | Service life increased 300%, with reduced labor costs by decreasing maintenance schedule from 6 months to 18 months. The potential of contaminating local waterways with oil was reduced, helping to avoid incurring fines of \$100,000 per occurrence. |
| | Power Generating Application |
| CASE 2: | Coal pulverizer grinding wheel |
| BEARING TYPE | Tapered roller bearings, HH249910/HH249949 & EE350750/EE350351 |
| CONDITIONS: | Coal dust caused bearing seizure, resulting in the dust being ignited. Bearing life 9 months. |
| | |
| Results: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. |
| Results: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications |
| Results: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens |
| RESULTS: CASE 3: BEARING TYPE | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens 5208EENR, double row ball bearings |
| RESULTS: CASE 3: BEARING TYPE CONDITIONS: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens 5208EENR, double row ball bearings Water, chips, dust and dirt penetrated the bearings. Bearing life 4 weeks. |
| RESULTS: CASE 3: BEARING TYPE CONDITIONS: RESULTS: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens 5208EENR, double row ball bearings Water, chips, dust and dirt penetrated the bearings. Bearing life 4 weeks. Bearing life has been extended from 4 weeks to over 4 months. |
| RESULTS: CASE 3: BEARING TYPE CONDITIONS: RESULTS: CASE 4: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. |
| RESULTS: CASE 3: BEARING TYPE CONDITIONS: RESULTS: CASE 4: BEARING TYPE | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens 5208EENR, double row ball bearings Water, chips, dust and dirt penetrated the bearings. Bearing life 4 weeks. Bearing life has been extended from 4 weeks to over 4 months. Baghouse dust conveyor bearings - wafer board manufacturer Flanged ball bearing units, 2-15/16" bore |
| RESULTS: CASE 3: BEARING TYPE CONDITIONS: RESULTS: CASE 4: BEARING TYPE CONDITIONS: | Used in addition to conventional lubrication, MicroPoly has kept contaminants out of the bearings. Life of the oil bath has increased twofold and is now changed out every 6 months. Bearing life has been extended to 10 years. Maintenance related downtime has been substantially reduced, with annual cost savings of \$250,000. Wood Product Applications Idler bearing in 120 roller chain sprockets in forest products machinery, slicers, feeders & bar screens 5208EENR, double row ball bearings Water, chips, dust and dirt penetrated the bearings. Bearing life 4 weeks. Bearing life has been extended from 4 weeks to over 4 months. Baghouse dust conveyor bearings - wafer board manufacturer Flanged ball bearing units, 2-15/16" bore Wood dust and atmospheric humidity. Bearings changed every 3 months. Bearings are outdoors and exposed to moisture. Speed 600 RPM. |





С

A S

Π

S

0

Π

R

S

MISCELLANEOUS APPLICATIONS FILLED BEARINGS

| CASE 5: Tro | enching equipment |
|---|---|
| BEARING TYPE: | Guide wheels and idler wheels, 22308 spherical roller bearing (axle bearing) FYRP 2-1/2" roller bearing |
| CONDITIONS: | Trenchers run in dusty, dirty, muddy conditions. Dirt and mud are pulled up and packed into the housings around the bearings. Idler wheels and axle bearings were replaced every month. Roller bearings were replaced every 2 months. |
| RESULTS: | Idler wheels and axle bearings filled with MicroPoly have been in service for almost a year. Life of the FYRP roller bearings was extended from 2 months to 2 years. |
| | Cement & Ceramic Applications |
| CASE 6: Pa | cker head (hydro tile) – concrete pipe manufacturer |
| BEARING TYPE: | Fafnir 1106KKR, 1108KKR, 1203 |
| CONDITIONS: | Sand and concrete contamination. Bearings are outdoors. Bearing life 1-2 days. Speed 100 RPM. |
| RESULTS: | Discontinued monitoring after 6 weeks. Results exceeded expectations. |
| CASE 7: De | palletter, telescoping section |
| BEARING TYPE: | Needle roller bearing, 1-3/4" - GR 32 – GR 40 |
| CONDITIONS: | Concrete dust contamination. Bearing life 3-4 months. Speed 178 RPM. |
| RESULTS: | Bearing life extended to at least 2-1/2 years. |
| CASE 8: Pa | inting spindle bearing – ceramic plate manufacturer |
| BEARING TYPE: | R6ZZ single row ball bearing |
| CONDITIONS: | Paint and solvents contamination. Bearing life 1-2 days. Speed 5-10 RPM. |
| RESULTS: | Bearing life has been extended to at least 30 days. |
| | Chemical Applications |
| | agline – vertical rotating shaft; lower bearing – fertilizer plant |
| CASE 9: Dr | |
| CASE 9: Dr BEARING TYPE: | Spherical roller bearing, #22315 |
| CASE 9: Dr BEARING TYPE: CONDITIONS: | Spherical roller bearing, #22315 Dirt and gypsum contamination. Bearing life 1-1/2 months. |
| CASE 9: Dr BEARING TYPE: CONDITIONS: RESULTS: | Spherical roller bearing, #22315 Dirt and gypsum contamination. Bearing life 1-1/2 months. Bearing life has been extended to over 1 year. |
| CASE 9: Dr BEARING TYPE: CONDITIONS: RESULTS: CASE 10: La | Spherical roller bearing, #22315 Dirt and gypsum contamination. Bearing life 1-1/2 months. Bearing life has been extended to over 1 year. mination line – foam plant |
| CASE 9: DR BEARING TYPE: CONDITIONS: RESULTS: CASE 10: La BEARING TYPE: | Spherical roller bearing, #22315 Dirt and gypsum contamination. Bearing life 1-1/2 months. Bearing life has been extended to over 1 year. mination line – foam plant McGill cam follower |
| CASE 9: Dr BEARING TYPE: CONDITIONS: RESULTS: CASE 10: La BEARING TYPE: CONDITIONS: | Spherical roller bearing, #22315 Dirt and gypsum contamination. Bearing life 1-1/2 months. Bearing life has been extended to over 1 year. mination line – foam plant McGill cam follower Required manual greasing that involved shutting down the equipment/line for at least 5 hours. Bearing life not a primary consideration. |





С

A S

Π

S

0

R

S

MISCELLANEOUS APPLICATIONS FILLED BEARINGS

| | Eastener Application |
|---------------|--|
| CASE 11. Tran | sfer application |
| BEARING TYPE: | 61902 & 61903, single row ball bearings |
| CONDITIONS: | Dirt and contaminated oil penetrated the bearings causing premature failure. |
| RESULTS: | Bearing life has been extended threefold. |
| | |
| | Wire Drawing Application |
| CASE 12: Wire | e drawing – bottom of wire reels |
| BEARING TYPE: | Single row ball bearing, 6204 |
| CONDITIONS: | Fines from the copper wire were getting into the bearing, causing bearings to fail in 2 months. |
| RESULTS: | Bearing life has been extended to 6-8 months. |
| | |
| | Mattress Manufacturer Application |
| CASE 13: 430 | 0 Gribitz sewing machine |
| BEARING TYPE: | Cam Followers |
| CONDITIONS: | Manual lubrication of cam followers caused grease and oil to get on the bed material. This caused staining, which resulted in loss of product. |
| RESULTS: | MicroPoly has stopped the lubrication staining, thus eliminating the need to scrap bed material due to staining from grease and oil. |
| | |
| | Agriculture Application |
| CASE 14: Disk | (harrow |
| BEARING TYPE: | Pillow block |
| CONDITIONS: | Water, dirt, and mud. Bearings are outdoors. Bearing life varies. |
| RESULTS: | Bearing life extended at least threefold. |
| CASE 15: Auto | omated mulch bagging |
| BEARING TYPE: | 20 mm single row ball bearings |
| CONDITIONS: | Bearings exposed to grit, moisture, and heat from bag sealers. Bearing life was 6 months. |
| RESULTS: | Bearings were filled with MicroPoly formula MPI-0779. Bearing life extended over 18 months. |
| | |
| | Petrochemical Application |
| CASE 16: Top | feed roll |
| BEARING TYPE: | Self-aligning ball bearing |
| CONDITIONS: | Bearings were running in a wet environment. Bearing speed 1,100 RPM. Temperature 130-140°F. Bearing life 2-3 weeks. |
| RESULTS: | MicroPoly filled bearings have been running for 3 months so far with no failures. |
| | |





C

5

Ц

H

MISCELLANEOUS APPLICATIONS FILLED BEARINGS

| Aggregate Application | |
|-----------------------|---|
| CASE 17: Hea | d & tail shaft pulleys in metal processing/mining |
| BEARING TYPE: | Rexnord, 2-15/16" bore |
| CONDITIONS: | Sand and water contamination. Bearing life 3 months. Speed 850 to 1370 RPM. |
| RESULTS: | With MicroPoly, bearing life has been extended over 18 months. |

0

R

Ц

S

CASE 18: Mineral processing, magnesite

S

| BEARING TYPE: | 4- bolt flange bearing |
|---------------|--|
| CONDITIONS: | Heated material in screw conveyor solidifies if the process is shut down. Bearing failure due to contamination was the primary cause of the shutdown. To remove the material, the screw assembly must be removed and the material must be chiseled out. The process is lengthy and expensive. Bearing life was less than one year. |
| RESULTS: | MicroPoly kept the contaminants out of the bearing. MicroPoly bearings lasted more than 3 years. Cost savings estimated in the tens of thousands. |

CASE 19: Railroad - rail grinding machine

| BEARING TYPE: | Spherical insert bearing |
|---------------|---|
| CONDITIONS: | Outdoor application. Debris from railroad rail grinding machine operation caused grease bearings to fail in 2-6 months. Since rail time for grinding is limited, down time reduces the effectiveness of the machines. |
| RESULTS: | MicroPoly filled bearings extended the life to 2 years. |

CASE 20: Manufacturer of roofing products

| BEARING TYPE: | Sealmaster NP 16 1-3/16" |
|---------------|--|
| CONDITIONS: | Paper goes through the looping line where tar is applied. The tar contaminates the bearings and normal life for a greased bearing is 1 week. |
| RESULTS: | With MicroPoly installed, the bearings were still running after 4 weeks. |

Printing Applications

CASE 21: Printing press

BEARING TYPE: Needle roller bearing, HJ4055228

CONDITIONS: Too much heat generated with previous lubrication method, and a severe housekeeping problem existed. Speed up to 1200 RPM.

RESULTS: Totally eliminated housekeeping problem. Greatly improved the performance of the printing press by reducing the thermal changes in the press, due to the bearings operating at much cooler temperatures.





Α

S

Ц

H

С

MISCELLANEOUS APPLICATIONS FILLED BEARINGS

| Textile Application | |
|---------------------|---|
| CASE 22: | Carpet manufacturing – tufting machines |
| BEARING TYPE | : Thrust and needle roller bearings |
| CONDITIONS: | Oil and grease leakage stained carpet and the bearings failed after processing 1 million feet of carpet (about 2 months). |
| RESULTS: | MicroPoly filled bearings lasted over 6 million feet (1 year and still running). Carpet staining by oil and grease was eliminated. |

R

0

Ц

S

5

Paper Processing CASE 23: Winder for mandrel on paper converter BEARING TYPE: 1204ETN9, double row ball bearings CONDITIONS: Abrasive tissue and paper dust locked up the bearings. Heavy loads; roll is as big as a car. Bearing life 2.5 months. RESULTS: MicroPoly keeps the contamination out of bearings. Bearing life extended to 1 year.

CASE 24: Idler rolls on paper converted for tissue and towels

| BEARING TYPE: | 6203 and 6205, single row ball bearings |
|---------------|---|
| CONDITIONS: | Abrasive tissue paper and dust contaminate the bearings, causing premature failure. Bearing life 1 month. |
| RESULTS: | MicroPoly kept the contamination out of bearings. Bearing life extended to 1 year. |





С

A S

MISCELLANEOUS APPLICATIONS SOLID PROFILES

| E | H I S T O R I E S |
|-------------|--|
| | Plastic Application |
| CASE 25: | Chain guide for "puller block" in conjunction with extruder |
| | 1" x 2" x 12" chain lube block |
| CONDITIONS: | Frictional heat on expensive profiled UHMW chain guide caused softening of guide and replacement of 40 blocks, 2 or 3 times per year. |
| Results: | Customer cuts MicroPoly blocks into 6" lengths and machines sides down to provide two raised shoulders. MicroPoly has doubled the life of the UHMW. Change out on the guides had cost customer \$500 per block. 40 blocks x 2 changes per year saved \$20,000. |
| | Aggregate Application |
| CASE 26: | Trunion scrubber for asphalt |
| MICROPOLY: | Solid profile installed in metal plate |
| CONDITIONS: | The surfaces had to be greased daily and, if not, metal would wear out and cause trunion to track off and shove bearings out of their housings. |
| RESULTS: | MicroPoly has been installed 3 months. No additional lubrication needed. Labor savings has been substantial. |
| | Furniture Manufacturing Application |
| CASE 27: | Wood board conveyor |
| MICROPOLY: | Conveyor chain lubrication, #80 chain, 50' long, and 24' center distance with 8" sprockets |
| CONDITIONS: | Chain moves 1 revolution every 2 minutes. Manual greasing of chain required every 4 weeks. This manual greasing contaminated the boards and dripped grease onto the floor, creating safety and housekeeping problems. |
| RESULTS: | MicroPoly blocks have been in place more than 6 years. Manual greasing has been eliminated, thus, solving the safety and housekeeping problems. |
| | Waste Treatment Application |
| CASE 28: | Sludge life chain |
| MICROPOLY: | MicroPoly 1" x 2" x 8" lubrication block is used to lubricate conveyor chain |
| CONDITIONS: | Water and dirt get into pins. Chain life is very short. Application is indoors. |
| RESULTS: | Results are very good. All conveyor chains are now lubricated in this manner. |
| | |

